BioCommand® Plus Software Update – Version 3.30

Description of changes:

Improves communications and supervisory control to the reactor controllers. Required with RPC controller (BioFlo®/CelliGen® 115, BioFlo 310, and BioFlo 415). Use this file only if your software is BioCommand Plus, version 3.30.

NOTE: This update is only for BioCommand Plus 3.30 customers. All other versions of BioCommand Software are not compatible with this software update.
To determine which version software you currently have installed:

> Open your BioCommand software program on your PC.
> The first screen that comes up identifies both the name (ie. BioCommand Plus) and version number of your software. If you have BioCommand Plus 3.3, proceed with the following update.

Instructions:

NOTE: Some virus scan software programs incorrectly identify this file as containing a virus, preventing you from running. In that instance, your MIS/IT Department can advise you on disabling your virus scan software before proceeding.

1. Select the basic windows [Start] button and then select the 'Run…' from the bottom right. Select the [Browse…] button as shown below and navigate to the folder where the file 'BioCommand Plus SP1.exe' exists. Select the [OK] button to start the Setup Wizard.

2. The following screen should appear. Select the [Next >] button to start the installation.

3. At the end of the installation procedure, the following screen will appear. Select the [Finish] button to end the Setup Wizard program.

Congratulations! You have installed the BioCommand Plus SP1 to enhance software communications.